



Phoenix-Goodyear Airport Superfund Site Overview: North and South Areas

Catherine Brown, EPA Project Manager

November 3, 2016

CAG Meeting
City of Goodyear Justice Facility
Goodyear, AZ

Agenda





Tonight's Topic

- Area Between the Sites Study
 - >PGAN
 - > PGAS

Questions & Answers

Outline





- Objectives of the Data Evaluation
- Background
- Findings
- Data Gaps and Next Steps

Objective





The overall objectives of this study are:

- □ Define the boundaries of Subunit A & C TCE plumes;
- ☐ Define the boundaries of Subunit A PCE plume;

Objective (cont'd)





To accomplish these objectives, the following effort was made:

- ☐ Summarize the water quality information from the recent groundwater investigations;
- ☐ Evaluate hydrogeological information based on recent and historical groundwater investigations;
- ☐ Evaluate relevant historical water quality data;

Background





PGAN

□ Performed additional investigation in 2015
☐ Installed 13 monitoring wells and 3 soil borings
☐ Drilled with either percussion hammer or a sonic rig
☐ High resolution lithological logs developed
☐ Depth-specific groundwater analytical data were obtained at
20 feet or shorter interval

• PGAS

□ 2015 Building 6 investigation
☐ Installed 4 monitoring wells and 1 soil boring
☐ Installed 2 Subunit C monitoring wells in 2016 to define
boundaries of the Northern Subunit C TCE plume
☐ Drilled with a sonic rig
☐ High resolution lithological logs developed
☐ Depth-specific groundwater analytical data were obtained at a
20 feet or shorter interval

Background (cont'd)





- Geochemical and isotope analysis from a select set of groundwater wells from the three sites;
- Concurrent quarterly water level measurement and data sharing.

Findings





- Subunit A TCE Plume
 - PGAN plume is defined by newly installed monitoring wells & soil borings
 - PGAS is also defined by existing and new wells
 - ➤ The divide between the two Subunit A plumes is generally along Yuma Road
- The PGAN Southeast Area Subunit A TCE Plume
 - ➤ Originated from the accidental injection of untreated water in the MTS injection well field

 U.S. EPA REGION 9

Findings





- Vertical Distribution of TCE/Perchlorate
 - ➤ The northern 5 ug/L boundary of the PGAS northern Subunit C TCE plume is likely located between GMW-37UC and EPA MW-66A, although the TCE concentration at depths below 200 feet bgs is not currently known.
 - ➤ The exact depth of the bottom of Subunit B near EPA MW-66A needs further evaluation.

Data Gaps and Next Steps





- Further evaluation of new and existing data is ongoing
- Assess the need for additional Subunit C monitoring wells, if any, as the vertical extent is undefined
- Evaluation of the top and bottom of Subunit B required

Data Gaps and Next Steps (cont'd)





- The PGAN team is developing a containment and capture work plan to address the contamination for the PGAN Subunit A TCE plume between the MTS injection field and Yuma Road.
- The PGAS team is considering groundwater remedy optimization for their northern Subunit C plume.

Technical Contacts





Contacts

Catherine Brown, EPA RPM

brown.catherine@epa.gov

Wayne Miller, ADEQ PGA PM

miller.wayne@azdeq.gov

Community Involvement Contacts



Wendy Flood, ADEQ Community Involvement Coordinator flood.wendy@azdeq.gov

http://www.epa.gov/superfund/phoenix-goodyearairport

http://legacy.azdeq.gov/environ/waste/sps/Phoenix-Goodyear_Airport_North.html

http://legacy.azdeq.gov/environ/waste/sps/Phoenix-Goodyear_Airport_South.html